ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	7	Byatarayanapura
Street ID	**Street Name**	**Significant Landmark**
W0139, W0086, W0141, W0155	NA	Jakkur Layout
Segment No.	**Total Length (m)**	
7/S-W0139/S035905	329.10	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	69.06	77.600525	13.071403	77.600383	13.070795	8th A Cross	Main Road
2	58.87	77.599041	13.070957	77.598917	13.070439	8th B Cross	Main Road
3	87.93	77.599288	13.071698	77.599041	13.070945	5t B Cross	Dead End
4	113.24	77.599542	13.072789	77.599319	13.071789	4th B Cross	Main Road

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to drains of 7th to 10th Cross Roads of Jakkur Layout in ward no 07, Byatarayanapura, Kodigehalli Sub Division	5000000	2017-18
Year	**Type of Work**	**Other Work Type**
2017 - 2018	Road	
Tender	**Work Details**	**Job No. / Work Code**
Not a Tender	1. Construction of RCC Drain.2.Providing and Laying Concrete Covering Slabs.	007-18-000006
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/84/17-18	02/03/2018	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
25/09/2018	24/09/2018	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
M/s Executive Engineer, K.R.I.D.L		0.00
Phone No.	**E-Mail ID**	

9449863065

Field Inspection Details

Number of Trees	Any Other Information	Name
0		Pushpalatha.N.D
Date of Inspection	**Remarks**	
18/12/2018		

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 7 **Ward Name:** Byatarayanapura **Street ID:** W0139, W0086, W0141, W0155

Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	Sri.R.L.Parameshwaraiah	05/01/2019	17/01/2019	Approved
SE	Basavaraj R Kabade	05/01/2019	17/01/2019	Forwarded
EE	Mohandas H.T	05/01/2019	17/01/2019	completed
AEE	H.Ranganath	18/12/2018	17/01/2019	Verified
AE	Pushpalatha.N.D	18/12/2018	17/01/2019	Mobile Verification Done
AE	Pushpalatha.N.D	18/12/2018	17/01/2019	Forwarded

Zone: YELAHANKA **Ward No:** 7 **Ward Name:** Byatarayanapura **Street ID:** W0139, W0086, W0141, W0155